

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 N/A	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Hillcap Ave. Hill Side: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
1/13/25	0.0019	< 0.0010	< 0.0010	0.0027	< 0.0010	0.029	< 0.0010	0.0027	< 0.00090	0.0039	0.0039
1/14/25	< 0.0010	< 0.0010	< 0.0010	0.0019	0.001	0.0019	0.0019	0.0028	< 0.00090	0.0009	< 0.00090
1/15/25	< 0.00090	0.0009	< 0.00090	< 0.00090	pump fault	< 0.00090	< 0.00090	0.0009	< 0.00090	0.0019	< 0.00090
1/16/25	0.001	<0.00090	<0.00090	<0.00090	<0.00090	<0.00090	<0.00090	0.004	<0.0010	0.002	0.001
1/17/25	< 0.00090	< 0.00090	0.001	< 0.00090	0.0009	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.