

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Hillcap Ave. Hill Side: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
1/27/25	0.0035	< 0.00090	< 0.00090	< 0.00090	0.0053	pump fault	0.0018	0.0018	< 0.00090	0.0097	0.0088
1/28/25	0.0019	< 0.00090	< 0.00090	< 0.00090	< 0.00090	0.0077	< 0.00090	0.0029	0.0019	0.011	0.0077
1/29/25	< 0.00090	< 0.00090	< 0.00090	0.0019	0.0009	0.001	0.001	0.0056	< 0.00090	0.0028	0.0019
1/30/25	< 0.0010	< 0.00090	< 0.00090	< 0.00090	< 0.0010	< 0.0010	< 0.0010	< 0.00090	< 0.00090	0.0019	0.0009
1/31/25	< 0.0010	0.001	0.0029	0.001	< 0.00090	< 0.0010	< 0.0010	0.001	< 0.0010	< 0.0010	0.001

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.