

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
03/03/25	< 0.0010	< 0.0010	< 0.00090	0.0019	0.0076	0.001	< 0.0010	0.0047	0.0009	0.0028	0.01
03/04/25	0.0009	0.0037	0.0027	0.0018	0.013	0.0055	0.0027	0.029	0.0055	0.018	0.012
03/05/25	No Grading Activities										
03/06/25	No Grading Activities										
03/07/25	< 0.00090	< 0.00090	< 0.00090	0.0009	0.0018	0.0062	0.0045	0.0079	0.0026	0.0026	0.014

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.