

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
3/17/25	No Grading Activities										
3/18/25	No Grading Activities										
3/19/25	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	0.0018	0.0036	0.0009	< 0.00090	0.0036
3/20/25	< 0.00090	< 0.00090	< 0.00090	< 0.00090	0.0044	0.0036	< 0.00090	0.0018	0.0036	0.0009	0.0009
3/21/25	< 0.00090	< 0.00090	0.0036	< 0.00090	0.0064	0.0036	0.0046	0.0046	< 0.00090	< 0.00090	0.0009

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.