

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Hillcap Ave. Hill Side: Exterior Perimeter	Station 12 Hillsdale Ave SE Location: Exterior Perimeter	Station 13 Hillsdale Ave. N Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
10/07/24	< 0.00090	0.0068	< 0.00090	0.013	pump fault	pump fault	< 0.00050	0.0009	pump fault	< 0.00090	0.0009	0.009	Out of scope - No grading operations
10/08/24	< 0.00090	< 0.0010	< 0.00090	< 0.00090	< 0.0010	pump fault	0.003	0.0018	0.0009	0.0009	< 0.00090	0.0082	
10/09/24	0.0009	< 0.00090	< 0.00050	< 0.0010	< 0.0010	< 0.0010*	< 0.0010*	0.001	< 0.00090	< 0.00090	0.0028	0.0057	
10/10/24	< 0.00090	< 0.00090	< 0.0010	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	0.0019	0.0019	
10/11/24	< 0.0010	< 0.0010	< 0.0010	< 0.0010	< 0.0010	< 0.0010*	< 0.00050	< 0.00090	< 0.00090	< 0.0010	< 0.00090	0.0038	

\* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.