

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Hillcap Ave. Hill Side: Exterior Perimeter	Station 12 Hillsdale Ave SE Location: Exterior Perimeter	Station 13 Hillsdale Ave. N Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
10/14/24	< 0.00090	< 0.00090	< 0.00090	0.0009	< 0.00090	< 0.00090	< 0.00090	< 0.00090	0.0028	< 0.00090	0.0028	0.037	Out of scope - No grading operations
10/15/24	< 0.00090	0.0009	< 0.00090	< 0.00090	< 0.00090	0.0018	< 0.00090*	0.0027	< 0.00090	0.0018	0.0009	0.012	
10/16/24	0.002	< 0.0010	< 0.00090	< 0.0010	< 0.0010	< 0.00090	0.0045	0.027	0.0029	0.002	0.001	0.034	
10/17/24	< 0.00090	< 0.00090	pump fault	< 0.00090	0.0049	0.0019	< 0.00090	0.015	0.021	0.0065	0.0047	0.0037	
10/18/24	0.0036	0.0027	< 0.00090	0.0018	< 0.00090	< 0.00090	< 0.00090	0.016	0.012	0.021	0.0064	0.015	

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.