

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Hillcap Ave. Hill Side: Exterior Perimeter	Station 12 Hillsdale Ave SE Location: Exterior Perimeter	Station 13 Hillsdale Ave. N Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
10/21/24	< 0.00090	< 0.00090	< 0.0010	< 0.00090	< 0.00090	0.0018	0.0027	0.0027	0.0018	< 0.00090	0.0054	0.016	Out of scope - No grading operations
10/22/24	0.0088	0.0058	0.0027	0.027	< 0.0010	0.0038	< 0.0010	0.001	< 0.0010	0.0069	0.0019	0.0068	
10/23/24	< 0.0010	pump fault	< 0.00090	< 0.0010	0.001	< 0.0010	0.0027*	< 0.0010	< 0.0010	< 0.0010	< 0.0010	0.02	
10/24/24	<0.00050	0.0037	< 0.00090	0.0009	< 0.00090	0.0018	0.0009	0.0055	0.0073	0.01	0.0073	0.018	
10/25/24	0.0019	0.001	0.011	0.0048	0.001	0.0019	< 0.0010*	0.0037	0.0009	0.0009	0.0047	0.0084	

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.