

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 N/A	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Hillcap Ave. Hill Side: Exterior Perimeter	Station 12 Hillsdale Ave SE Location: Exterior Perimeter	Station 13 Hillsdale Ave. N Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
10/28/24	< 0.00090	< 0.00090	pump fault	< 0.00050	0.0018	0.0009	0.0066	0.0084	0.0009	0.0066	0.0037	0.0037	Out of scope - No grading operations
10/29/24	0.0009	< 0.00090	< 0.00080	< 0.00090	< 0.00090	0.0019	< 0.00090	< 0.00090	< 0.00090	0.0019	0.0019	0.0047	
10/30/24	0.0028	0.0019	0.0045	0.0019	< 0.00090	0.0038	0.0038	0.0009	0.0038	0.0057	< 0.00090	0.0076	
10/31/24	0.0019	0.0019	0.0019	0.0047	0.0028	0.045	0.0019	0.015	0.0057	0.0029	0.0067	0.0009*	
11/01/24	< 0.00090	< 0.00090	0.0027	0.0009	0.0009	0.0009	0.0009	0.0018	0.0027	< 0.00090	0.0009	N/A	

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.