

| | Station 1 NW Railroad: Exterior Perimeter | Station 2 SW Ridgline: Exterior Perimeter | Station 3 N/A | Station 4 Altino and Donnici Corner: Exterior Perimeter | Station 5 Altino Blvd Park: Exterior Perimeter | Station 6 Fire Station Exterior Perimeter | Station 7 Empoli St: Exterior Perimeter | Station 8 Lina St Construction Entry: Exterior Perimeter | Station 9 Communications Hill Blvd Hill: Exterior Perimeter | Station 10 Railroad Center: Exterior Perimeter | Station 11 Hillcap Ave. Hill Side: Exterior Perimeter | Station 12 Hillsdale Ave SE Location: Exterior Perimeter | Station 13 Hillsdale Ave. N Quarry Entrance: Exterior Perimeter |
|---------|--|--|------------------|--|--|---|---|---|--|--|--|---|--|
| Date | str/cc | str/cc | str/cc | str/cc | str/cc | str/cc | str/cc | str/cc | str/cc | str/cc | str/cc | str/cc | str/cc |
| 11/4/24 | 0.0099 | < 0.00050 | < 0.0010 | < 0.0010 | 0.034 | 0.015 | 0.0009 | 0.0009 | 0.0057 | < 0.0010 | < 0.0010 | 0.0046 | Out of scope - No grading operations |
| 11/5/24 | NO EARTHWORK ACTIVITIES | | | | | | | | | | | | |
| 11/6/24 | NO EARTHWORK ACTIVITIES | | | | | | | | | | | | |
| 11/7/24 | 0.001 | < 0.0010 | < 0.0010 | < 0.0010 | 0.001 | < 0.0010 | 0.001 | < 0.00050 | < 0.0010 | 0.001 | < 0.0010 | 0.0029 | |
| 11/8/24 | < 0.00090 | < 0.00090 | 0.0029 | 0.0009 | < 0.00090 | 0.0036 | < 0.00090 | 0.0009 | 0.0009 | 0.0009 | 0.0027 | 0.003 | |