

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 N/A	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Hillcap Ave. Hill Side: Exterior Perimeter	Station 12 Hillsdale Ave SE Location: Exterior Perimeter	Station 13 Hillsdale Ave. N Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
11/11/24	NO EARTHWORK ACTIVITIES												Out of scope - No grading operations
11/12/24	0.001	0.001	< 0.00090	< 0.0010	0.001	0.0039	0.0039	0.0019	0.0084	0.001	0.0019	0.0076	
11/13/24	0.0028	0.0009	0.0009		0.0075	0.016	0.0056	0.01	0.0087	< 0.0010	0.0019	0.0047	
11/14/24	<0.0010	0.0019	< 0.0010	< 0.0010	< 0.0010	0.001	0.0019	0.01	< 0.0010	0.001	< 0.0010	0.0067	
11/15/24	< 0.00090	< 0.00090	< 0.0010	< 0.00090	< 0.00090	0.021	0.0009	pump fault	0.0035	< 0.00090	0.0018	< 0.00090	

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.