

Comm Hill 2 Phase II Perimeter Sample Results

Week of November 21st through November 25th, 2022

Sampling Date	P1			P2			P3			P4			P5		
	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³
11/21/2022				2	4	0.0059							ND	ND	<0.0010
11/22/2022				ND	ND	<0.0010							ND	ND	<0.0010
11/23/2022				ND	ND	<0.0010							Equipment stolen - No Sample		
11/24/2022															
11/25/2022															
BAAQMD Guidelines												<0.016 Structures/cc			

Sampling Date	P6			P7			P8			P9d			P10e		
	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³
11/21/2022	ND	ND	<0.0010	2	2	0.0039	1	ND	0.0010	ND	ND	<0.0010	ND	ND	<0.0010
11/22/2022	1	ND	0.0010	ND	2	0.0020	ND	1	0.0010	2	ND	0.0020	1	ND	0.0010
11/23/2022	ND	ND	<0.0010	ND	ND	<0.0010	ND	ND	<0.0010	ND	ND	<0.0010	ND	1	0.0010
11/24/2022															
11/25/2022															
BAAQMD Guidelines												<0.016 Structures/cc			

1 - Chrysotile Asbestos

2 - Amphibole Asbestos - Including regulated and non-regulated amphibole asbestos

3 - Structures/CC - Calculated Asbestos Structure Concentration per CC Air

ND Not Detect

BAAQMD Guidelines Trigger Level for increased dust control measures

NM Not Measured

1/20/2022 Sampling Location moved from P10d to P10e