

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 N/A	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Hillcap Ave. Hill Side: Exterior Perimeter	Station 12 Hillsdale Ave SE Location: Exterior Perimeter	Station 13 Hillsdale Ave. N Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
12/02/24	0.0019	< 0.0010	< 0.00090	< 0.0010	0.001	< 0.0010	< 0.0010	< 0.00090	< 0.00090	0.0029	< 0.0010	0.0019	Out of scope - No grading operations
12/03/24	< 0.00090	< 0.00090	< 0.00090	< 0.0010	< 0.0010	0.001	< 0.0010	0.0009	0.0009	< 0.00090	0.0009	0.0038	
12/04/24	0.0038	< 0.00090	< 0.00090	0.0029	0.002	0.001	< 0.0010	< 0.00090	0.0009	0.0019	< 0.00090	0.0028	
12/05/24	< 0.0010	< 0.0010	< 0.0010	< 0.00090	< 0.00090	< 0.00090	0.0018	0.001	< 0.0010	< 0.0010	< 0.00050	< 0.0010	
12/06/24	< 0.00090	< 0.00090	pump fault	0.0009	< 0.00090	< 0.00090	< 0.00090	< 0.00090	0.0037	0.0037	0.0009	0.0075	0.0056

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.