

Comm Hill 2 Phase II Perimeter Sample Results
Week of July 13th through July 17th, 2020

Sampling Date	P1			P2			P3			P4			P5		
	Chrysotile	Amphibole	Structures /cc	Chrysotile	Amphibole	Structures /cc	Chrysotile	Amphibole	Structures /cc	Chrysotile	Amphibole	Structures /cc	Chrysotile	Amphibole	Structures /cc
7/13/2020	ND	ND	<0.0010	2	ND	0.0019	4	ND	0.0040	ND	ND	<0.0010	ND	ND	<0.0010
7/14/2020	1	ND	0.0009	ND	ND	<0.0010	1	ND	0.0009	3	ND	0.0030	4	ND	0.0037
7/15/2020	ND	ND	<0.0009	ND	ND	<0.0009	ND	ND	<0.0009	ND	ND	<0.0009	ND	ND	<0.0009
7/16/2020	ND	ND	<0.0010	ND	ND	<0.0010	ND	1	0.0010	2	ND	0.0020	2	ND	0.0020
7/17/2020	2	ND	0.0020	2	ND	0.0020	2	1	0.0030	1	ND	0.0010	1	ND	0.0010
BAAQMD Guidelines										<0.016 Structures/cc					

Sampling Date	P6			P7			P8			
	Chrysotile	Amphibole	Structures /cc	Chrysotile	Amphibole	Structures /cc	Chrysotile	Amphibole	Structures /cc	
7/13/2020	ND	ND	<0.0010	ND	ND	<0.0010	3	ND	0.0029	
7/14/2020	3	ND	0.0028	ND	ND	<0.0010	ND	ND	<0.0010	
7/15/2020	ND	ND	<0.0010	2	ND	0.0020	1	ND	0.0010	
7/16/2020	ND	ND	<0.0010	ND	ND	<0.0010	3	ND	0.0030	
7/17/2020	ND	ND	<0.0010	1	ND	0.0010	ND	ND	<0.0010	
BAAQMD Guidelines										<0.016 Structures/cc

1 - Chrysotile Asbestos

2 - Amphibole Asbestos - Including regulated and non-regulated amphibole asbestos

3 - Structures/CC - Calculated Asbestos Structure Concentration per CC Air

ND Indicates that no asbestos structures were detected in the grid openings scanned

BAAQMD Guidelines Trigger Level for increased dust control measures