

Weekly Data Log  
09/16/24 - 09/20/2024  
Communications Hill 2 Phase III and IV Project  
Exceedance Threshold >0.016 structures per cubic centimeter (str/cc)

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Hillcap Ave. Hill Side: Exterior Perimeter	Station 12 Hillsdale Ave SE Location: Exterior Perimeter	Station 13 Hillsdale Ave. N Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
09/16/24	< 0.0010	0.0009	0.0064	< 0.00090	pump fault	pump fault	0.0027	< 0.00090	0.0009	< 0.00090	< 0.00090	< 0.00090	Out of scope - No grading operations
09/17/24	< 0.0010	< 0.0010	< 0.00050	0.0067	pump fault	pump fault	< 0.0010	< 0.00090	0.0009	0.0048	< 0.00090	< 0.00090	
09/18/24	< 0.0010	< 0.00090	< 0.0010	< 0.00090	pump fault	pump fault	0.0035	0.0044	0.008	< 0.0010	0.004	0.015	
09/19/24	0.001	< 0.00090	0.001	< 0.00090	< 0.0010	pump fault	0.0009	0.0028	0.0029	0.001	0.0029	0.023	
09/20/24	< 0.00090	0.0018	< 0.00090	< 0.00090	< 0.00090	pump fault	< 0.00090	0.001	0.0009	pump fault	0.0004	0.012	