

Weekly Data Log
09/23/24 - 09/27/2024
Communications Hill 2 Phase III and IV Project
Exceedance Threshold >0.016 structures per cubic centimeter (str/cc)

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Hillcap Ave. Hill Side: Exterior Perimeter	Station 12 Hillsdale Ave SE Location: Exterior Perimeter	Station 13 Hillsdale Ave. N Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
9/23/24	< 0.00090	0.0009	0.0014	0.001	< 0.00090	0.0009	0.01	0.011	< 0.00090	0.0018	0.0099	0.014	Out of scope - No grading operations
9/24/24	pump fault	0.004	< 0.0010	0.0009	0.0057	0.0019	0.0037	0.0064	0.0083	pump fault	0.0028	0.0056	
9/25/24	0.0009	< 0.00090	< 0.00090	0.0009	0.0019	< 0.00090	0.0028	0.02	0.0019	< 0.00090	0.0051	0.01	
9/26/24	< 0.00090	< 0.00090	< 0.0010	< 0.00090	0.0026	0.004	0.001	< 0.00090	0.0009	0.0027	< 0.00090	0.0027	
9/27/24	< 0.00090	0.0028	0.001	0.0019	< 0.00090	0.001	< 0.00090	0.0009	0.0018	0.0019	< 0.00090	0.018	