Comm Hill 2 Phase II Perimeter Sample Results

Week of July 18th through July 22nd, 2022

Sampling Date	P1			P2			P3			P4			P5		
	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³
7/18/2022	No KB contractors performing earth disturbing activities.														
7/19/2022	No KB contractors performing earth disturbing activities.														
7/20/2022	No KB contra	ctors performi	ng earth disturbin	g activities.											
7/21/2022	No KB contra	ctors performi	ng earth disturbin	g activities.											
7/22/2022	No KB contra	ctors performi	ng earth disturbin	g activities.											

BAAQMD Guidelines

<0.016 Structures/cc

Sampling Date	Р6			P7			P8			P9d			P10e		
	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³
7/18/2022	No KB contra	ctors performi	ng earth disturbin												
7/19/2022	No KB contra	ctors performi	ing earth disturbin	g activities.											
7/20/2022	No KB contractors performing earth disturbing activities.														
7/21/2022	No KB contractors performing earth disturbing activities.														
7/22/2022	No KB contractors performing earth disturbing activities.														

BAAQMD Guidelines

<0.016 Structures/cc

2 - Amphibole Asbestos - Including regulated and non-regulated amphibole asbestos

3 - Structures/CC - Calculated Asbestos Structure Concentration per CC Air

ND Not Detect

BAAQMD Guidelines Trigger Level for increased dust control measures

NM Not Measured

1/20/2022 Sampling Location moved from P10d to P10e

^{1 -} Chrysotile Asbestos