

Comm Hill 2 Phase II Perimeter Sample Results
 Week of July 25th through July 29th, 2022

| Sampling Date | P1 | | | P2 | | | P3 | | | P4 | | | P5 | | |
|--------------------------|---|------------------------|----------------------------|-------------------------|------------------------|----------------------------|-------------------------|------------------------|----------------------------|--------------------------------|------------------------|----------------------------|-------------------------|------------------------|----------------------------|
| | Chrysotile ¹ | Amphibole ² | Structures/cc ³ | Chrysotile ¹ | Amphibole ² | Structures/cc ³ | Chrysotile ¹ | Amphibole ² | Structures/cc ³ | Chrysotile ¹ | Amphibole ² | Structures/cc ³ | Chrysotile ¹ | Amphibole ² | Structures/cc ³ |
| 7/25/2022 | | | | 3 | ND | 0.0028 | ND | ND | <0.0010 | | | | ND | ND | <0.0009 |
| 7/26/2022 | | | | ND | ND | <0.0010 | ND | ND | <0.0010 | | | | ND | ND | <0.0010 |
| 7/27/2022 | No KB contractors performing earth disturbing activities. | | | | | | | | | | | | | | |
| 7/28/2022 | No KB contractors performing earth disturbing activities. | | | | | | | | | | | | | | |
| 7/29/2022 | No KB contractors performing earth disturbing activities. | | | | | | | | | | | | | | |
| BAAQMD Guidelines | | | | | | | | | | <0.016 Structures/cc | | | | | |

| Sampling Date | P6 | | | P7 | | | P8 | | | P9d | | | P10e | | |
|--------------------------|-------------------------|------------------------|----------------------------|-------------------------|------------------------|----------------------------|-------------------------|------------------------|----------------------------|--------------------------------|------------------------|----------------------------|-------------------------|------------------------|----------------------------|
| | Chrysotile ¹ | Amphibole ² | Structures/cc ³ | Chrysotile ¹ | Amphibole ² | Structures/cc ³ | Chrysotile ¹ | Amphibole ² | Structures/cc ³ | Chrysotile ¹ | Amphibole ² | Structures/cc ³ | Chrysotile ¹ | Amphibole ² | Structures/cc ³ |
| 7/25/2022 | ND | ND | <0.0009 | ND | ND | <0.0009 | ND | ND | <0.0009 | ND | ND | <0.0009 | ND | ND | <0.0009 |
| 7/26/2022 | ND | ND | <0.0010 | ND | 2 | 0.0021 | 3 | 1 | 0.0042 | 1 | ND | 0.0010 | 3 | ND | 0.0031 |
| 7/27/2022 | | | | | | | | | | | | | | | |
| 7/28/2022 | | | | | | | | | | | | | | | |
| 7/29/2022 | | | | | | | | | | | | | | | |
| BAAQMD Guidelines | | | | | | | | | | <0.016 Structures/cc | | | | | |

1 - Chrysotile Asbestos

2 - Amphibole Asbestos - Including regulated and non-regulated amphibole asbestos

3 - Structures/CC - Calculated Asbestos Structure Concentration per CC Air

ND Not Detect

BAAQMD Guidelines Trigger Level for increased dust control measures

NM Not Measured

1/20/2022 Sampling Location moved from P10d to P10e