

Comm Hill 2 Phase II Perimeter Sample Results
 Week of August 1st through August 5th, 2022

Sampling Date	P1			P2			P3			P4			P5		
	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³
8/1/2022	No KB contractors performing earth disturbing activities.														
8/2/2022	No KB contractors performing earth disturbing activities.														
8/3/2022	No KB contractors performing earth disturbing activities.														
8/4/2022	No KB contractors performing earth disturbing activities.														
8/5/2022	No KB contractors performing earth disturbing activities.														
BAAQMD Guidelines										<0.016 Structures/cc					

Sampling Date	P6			P7			P8			P9d			P10e		
	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³
8/1/2022	No KB contractors performing earth disturbing activities.														
8/2/2022	No KB contractors performing earth disturbing activities.														
8/3/2022	No KB contractors performing earth disturbing activities.														
8/4/2022	No KB contractors performing earth disturbing activities.														
8/5/2022	No KB contractors performing earth disturbing activities.														
BAAQMD Guidelines										<0.016 Structures/cc					

1 - Chrysotile Asbestos

2 - Amphibole Asbestos - Including regulated and non-regulated amphibole asbestos

3 - Structures/CC - Calculated Asbestos Structure Concentration per CC Air

ND Not Detect

BAAQMD Guidelines Trigger Level for increased dust control measures

NM Not Measured

1/20/2022 Sampling Location moved from P10d to P10e